ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra

Street ID	Street Name	Significant Landmark
W1022, W1411, W1016, W1421, W1020, W1012, W1024, W	NA, 9th Crs, 12th Crs, 11th Crs, 15th Crs	Defence layout

Segment No.	Total Length (m)
6/C-W1022/S014517	398.48

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	60.18	77.625698	13.048314	77.625785	13.048851	Defence layout	1st Cross
2	59.09	77.626036	13.048257	77.626116	13.048785	Defence layout	2nd cross
3	84.75	77.626414	13.048214	77.626556	13.048963	Defence layout	3rd Cross
4	194.46	77.626811	13.048142	77.627334	13.049814	Defence layout	4th cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-1, includes 3 works of Rs.200.00 lakhs 1 Improvements to Roads and Drains at Sadiq Layout (Defence Layout) in Ward No. 06 Byatarayanapura Sub	20000000	2017-18

Year	Type of Work	Other Work Type
2017 - 2018	Others	B.S. slab drain and asphalting

Tender	Work Details	Job No. / Work Code
Tender	B.S. slab drain and asphalting	006-18-000056

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/61/2018-19	23/07/2018	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
23/07/2018	23/07/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M. Venkatesh		0.00

Phone No.	E-Mail ID

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh c naik

Date of Inspection	Remarks
18/05/2019	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1022, W1411, W1016, W1421,

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	22/05/2019	17/06/2019	As proposed
SE	Basavaraj R Kabade	22/05/2019	17/06/2019	Forwarded
EE	Mohandas H.T	22/05/2019	17/06/2019	approved
AEE	Sridhar B.S	18/05/2019	17/06/2019	verified
AE	Daramsingh C Naik	18/05/2019	17/06/2019	Mobile verifiction is done
AE	Daramsingh	18/05/2019	17/06/2019	forwarded

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1022, W1411, W1016, W1421,